



A HOBGING FOR TH



1. Hobbing device set up on lathe.

Protracted evolution

I made a start at gear hobbing around 1967 when I purchased a copy of an American publication "*Complete Metal working Manual*" by R. H. Cooley, which included a gear hobbing attachment that was supposed to generate worm, spur and helical gears. Although lacking a complete understanding of what was necessary at the time, I decided nevertheless to have a go and build the device. I made the casting and all the parts, including the hob, which was to be hand relieved. The hob was a lot of work and could only be sharpened once or twice before the relief was lost and it had to be renewed.



2. Workhead assembly on vertical slide

Dr. Giles Parkes excellent attachment described in MEW Iss. 57 pg. 37 solved the hob-forming problem. The gear hobbing attachment made use of the topslide as the vertical feed, and providing that you had a gear of the same number of teeth as was needed, would make usable spur gears. The expanding gear train did not allow worm gears, and helicals were not possible either. In addition, the overall rigidity was far from perfect.

Back in 2001 I wrote to 'Scribe a Line' in MEW Iss. 74 with a brief mention of a hobbing attachment that worked rather well. This device, shown in **Photo 1** is the final evolution of the above.

It is very easy to build and use, takes no space, can be set up in less than five minutes, does not require a worm gear, and costs next to nothing to make. The change gears of the lathe can be used initially until replacements are made. It cuts worm gears, spurs, and when I master the maths, will make helicals too. I have cut countless gears in tufnol, brass, cast iron and aluminium. They have been used in all sorts of applications and have worked very well. For those who question the wisdom of using a spur gear instead of a worm gear for the index gear. I will say that my aluminium index gear has worked for six years, cut over fifty gears and yet shows no wear that I can see. However if it ever does wear the device will readily produce a worm for those who want to go that route. The drawings have not been completely detailed, (for example the simple bolt and bush pivot for the idler gear), but in conjunction with the photographs, should convey sufficient

John Whalley describes an easily made but versatile attachment

information for most would be constructors. The slide shown, with the outboard leadscrew reduces the overhang by about 1.125in. from that provided by my topslide and goes a long way to reducing the rigidity problem if an angle bracket that is at least $\frac{7}{8}$ in. thick is used. Gears of about $\frac{5}{8}$ in. dia. can be made. I might add that when very small worm gears are required that use a hob that is too small to fit on the mandrel in the usual manner. I mount the hob in a chuck and drive the attachment from the tailstock end with a chain and small sprockets driven from the leadscrew to a long universal shaft that connects to the boss on the tail stock side of the worm that drives the index gear. The necessary gearing is mounted on the headstock quadrant, and sometimes gears are needed to clear the tailstock handwheel. I mention this only as an insight to what can be accomplished with a little perseverance.


The work head casting

In the original publication this was made from cast iron. I changed several dimensions to serve my needs and moved the mounting boss for the brackets to the opposite side of the casting. Since I have a small foundry it was no problem to cast in aluminium and has proved to be up to the job.

The casting needs to be milled flat on the top and bottom of the mounting boss, and the left rear side where the vertical



3. Change gear quadrant assembly



used, and many of you will find a way that no doubt suits you better. My arrangement of the vertical slide appears in **photo 5**. All running surfaces are in bronze bushings, which are not shown. The rather protracted arrangement of the change gear quadrant and various parts is to allow it to be assembled either in front of or behind the mandrel as may be required to produce very small wormwheels along the lines previously mentioned.

with a very rigid angle bracket (at least $\frac{1}{8}$ in. thick, $\frac{1}{4}$ in. is better) vertically on the cross slide so that the blank will be at the helix angle of the hob and able to be fed up and down parallel with it. It is worth mentioning that while the topslide can be used as a vertical slide, a purpose built one with much less overhang will work much better particularly when larger dia. gears are being hobbled.

The gear blank to be cut must revolve


counter clockwise as seen from above with a right hand threaded worm. (Hence the idler gear in the photos).

The blank works best 0.010in. undersize from normal dimensions usually used in gear cutting calculations. (feed in 0.005 in. less than root dia.)


Verify the helix angle of your hob with both a maths calculation and by placing a

Operation and set-up


With reference to the photos assemble the work head casting on the vertical slide



5. Workhead assembly showing vertical feed screw.



6. Detail of set up also showing tailstock support.



Before cutting a gear (say a 20T spur gear) start the machine in motion and verify the following:

- That you have 20 turns of the hob to one of the blank.
 - Turn in the cross slide until the centre of the blank just touches the revolving hob (set the cross slide at zero) and make sure that you have 20 notches cut on the blank. (if you don't you have either got your gear ratio wrong, or if the notches are not clearly defined, the blank is not revolving in the correct direction and will not generate a gear).
 - Wind the vertical slide up past the hob giving it time to cut all around and verify that the marks are at 90 deg. to the blank. (if not, correct this situation by adjusting the helix angle as required).
 - Wind back down, feed in the cross slide the root dia. minus 0.015in. (Lock the cross slide and I might mention the saddle must be locked also). Mark the gear blank with a felt pen, to give a visual indication of completed revolutions.
- Running the lathe just a bit slower than the usual milling speed advance the vertical feed about 0.050in. every turn of the blank, or whatever feed works best, allowing time for the hob to cut all around until you feed out of contact with the hob. Wind back down to the starting point (out of contact with the hob). Remove the gear arbor, marking it's position with a felt pen so that it can be replaced in exactly the same place as it was before. Measure the root dia. and replace. Feed in the necessary amount to finish the gear. Start the machine and check that everything lines up, then proceed to finish cutting the gear.

