





Pinout diagram for J5 connector (1x16 pins):

Pin	Signal
1	OUT0
2	GND-PWR
3	OUT1
4	GND-PWR
5	OUT2
6	GND-PWR
7	OUT3
8	GND-PWR
9	OUT4
10	GND-PWR
11	OUT5
12	GND-PWR
13	OUT6
14	GND-PWR
15	OUT7
16	GND-PWR

J5
Con 1x16



Pinout diagram for J6 connector (1x16):

Pin	Signal
1	IN0
2	GND-PWR
3	IN1
4	GND-PWR
5	IN2
6	GND-PWR
7	IN3
8	GND-PWR
9	IN4
10	GND-PWR
11	IN5
12	GND-PWR
13	IN6
14	GND-PWR
15	IN7
16	GND-PWR

Open Hardware