# **TECHNICAL DATA**

# Knurls & Knurling



fax: 1-508-595-0002

			-



# Reed Machinery's New Facility

Reed Machinery, Inc. became the new owner of the famous Reed thread rolling machine and attachment product lines in December, 2003 and relocated the operations back to their original home, Worcester, Massachusetts, in a modern facility formerly owned by Heald Machine.

The company is privately owned, with many employees having some share of ownership.

Technical expertise covers the range of machines and attachments used for thread and form rolling so you can be sure that you will get an objective recommendation about what type of process is best suited for your manufacturing situation.

Call, fax or email your thread rolling requirements to Reed Machinery, Inc. for a rapid, accurate response.

# **Contents**

# Knurling

More Than Seventy-Five Years of Thread Rolling
General Knurling Information 3
Circular Pitch Knurling 7
Diametral Pitch Knurling
Knurling on Screw Machines and Lathes 18
Knurling on Thread Rolling Machines 20
REED-RICO® Standard Knurls2
Disch Voyals


# General Knurling Information


### Description of the Process


Knurling has a wide variety of applications in the screw machine industry, many of its products having knurled surfaces. Knurling is most commonly used for decorative purposes and for serrating surfaces where component parts are locked or keyed together in unit assemblies.

The term knurling designates both the process and the knurled portion of the work. Knurling is obtained by displacement of the material when the knurl is pressed against the surface of a rotating work blank. Knurling tools are used for producing straight, diagonal or diamond knurling having teeth of uniform pitch on cylindrical surfaces.

Cylindrical knurls are used for knurling on screw machines, automatic lathes and cylindrical die thread rolling machines. The most commonly used knurls are those which produce straight, diagonal and diamond patterns on the work. Special knurls may be used, however, to produce teeth on tapered, convex or concave surfaces. Flat knurling dies are used in reciprocating types of thread rolling machines. Diamond knurling may have either a male or female pattern. Male diamond knurls have raised points and produce a female impression. Female diamond knurls have depressed points and produce a male impression. The male diamond pattern knurling with raised points on the work is most commonly used as it can easily be produced by using two diagonal knurls - one right hand and the other left hand. Single knurls with male or female diamond patterns are also used.











FIG. 1

### **Tooth Form**

A knurled tooth is V-shaped and the depth of the tooth is less than the depth of a theoretical V-form. The tooth has a rounded root and crest. The relationship between the actual depth of tooth to the theoretical V varies with the pitch of the teeth. On finer pitches, the tooth is a smaller proportion of the theoretical V-depth than coarser pitches. Also, female diamond patterns have shallower tooth depth than male diamond patterns.



### Circular and Diametral Pitch Systems

Two general methods of knurling are now in use — the circular pitch and diametrical pitch systems. The circular pitch system is the older and has been in use for many years. It is based on the circular pitch and teeth per inch formulae related to the circumference of the work. The diametral pitch system is covered by the American Standard ANSI/ASME B94.6-1984. Four standard diametral pitches, 64, 96, 128, and 160 are used for work diameters ranging from 3/32" through 1". The purpose of diametral pitch knurling is to permit work blank diameters of standard fractional stock sizes to be used. The 96 and 160 diametral pitches apply to work blank diameters in 1/32" diameter increments and the 64 and 128 diametral pitches are for work blank diameters in 1/64" diameter increments. REED-RICO® cylindrical knurls are available for both

systems which are fully described in separate sections of this booklet.

### **Methods of Applying Knurls**

The sequence of operations and the tooling for knurling is dependent upon the nature of the part and the type of equipment selected. The knurling tools on automatic lathes and screw machines are mounted on the cross slides or in the turrets for either in-feed or end-feed knurling, depending upon the type of knurling and the knurl holders used.

Both one and two knurls are used for in-feed knurling, while two knurls are always necessary for end-feed knurling. The method of feeding the knurl into the work varies with the position of the knurling on the work with respect to shoulders; also the type of knurl holder and the position of the holder on the machine. The common methods of applying the knurls are illustrated below. Figures 3, 4 and 5 show application of conical, convex and concave knurls.




Table 1
Knurling Produced from Cross Slide - One Knurl

		KNURL	SUSED	
TYPE OF FEEDING	STRAIGHT	L.H. DIAGONAL	R.H. DIAGONAL	FEMALE DIAMOND
IN-FEED With Side Knutl Holder	Straight	R.H. Diagonal	L.H. Diagonal	Male Diamond (Raised Points)

Table 2
Knurling Produced from Cross Slide - Two Knurls

		KNUR	S USED	
TYPE OF FEEDING	©0 ©0 STRAIGHT	L.H. DIAGONAL	RH. DIAGONAL	R. & L.H. DIAGONAL
IN-FEED With Side Knurl Holder WORK	Straight	R H. Diagonal	L.H. Diagonal	Male Diamond (Raised Paints)
IN-FEED With Adjustable Straddle Type Holder WORK	Stroight	R.H Diagonal	L.H Diagonal	Male Diamand- (Rassed Points)

Table 3
Knurling Produced from Turret - One Knurl

	KNURLS USED						
TYPE OF FEEDING	STRAIGHT	L.H. DIAGONAL	R.H. DIAGONAL	FEMALE DIAMOND			
IN-FEED With Swing Type Knurl Holder Actuated from Cross Slide WORK	Stroight	R.H. Diagonal	L.H. Diagonal	Male Diamond (Raised Points)			

Table 4
Knurling Produced from Turret - Two Knurls

		KNURL	S USED	
TYPE OF FEEDING	STRAIGHT	LH. DIAGONAL	R.H. DIAGONAL	R. & L.H. DIAGONAL
IN-FEED With Swing Type Knurl Holders In-Feed Actuated From Cross Slide	Straight	R.H. Diagonal	L.H. Diogonal	Male Diamond (Raised Points)
END FEED With Adjustable Knut Holder Actuated from Cross Slide WORK	Straight	R.H. Diagonal	L.H. Diogonal	Male Diamond (Raised Points)
END-FEED With Adjustable Knurl Holder WORK	Straight	R.H. Diagonal	L.H. Diagonal	Male Diamond (Raised Points)
END-FEED With Adjustable Swivel Type Knurl Holder WORK	Male Diamond (Raised Paints)			
END-FEED With Adjustable Swivel Type Knurl Holder  WORK	R.H. or L. H. Diagonal (R. H. Diagonal Shown)	Straight	Straight	

# REED-RICO® Circular Pitch Knurling

Circular pitch knurling is related to the distance between the teeth on the circumference of the work blank. It is usually expressed in terms of the number of teeth per inch, TPI, although sometimes erroneously referred to as pitch.

When knurling is used for decorative and general appearance purposes or for a hand grip, it is only necessary to specify the approximate teeth per inch, TPI, required for the knurling, thereby permitting standard knurls to be used.

Always specify the tooth pattern of the knurling, stating whether it is straight, diagonal or diamond pattern. Mention whether the diagonal knurling is right or left hand, whether diamond pattern is male or female, and indicate the angle of helix in both cases.

Knurling is sometimes referred to as coarse, medium and fine. Where no reference is made to diameters, 16-20 TPI is sometimes referred to as coarse, 25-35 as medium and 40-80 as fine. Much confusion has resulted from this practice because the size of the knurled diameter, in many instances, influences the selection of the pitch of the knurl to be used. What appears to

be a coarse pitch on a small diameter may seem like a medium or fine pitch on a large diameter. We therefore recommend that the knurling be specified on the basis of TPI-teeth per inch.

### Number of Teeth per inch-TPI

The number of teeth per inch is referred to as TPI. On REED-RICO® diagonal and diamond knurls "normal TPI" is used and is measured perpendicular to the teeth or helix angle.

In deciding the knurled pattern for a part, it is first necessary to determine whether straight, diagonal or diamond knurling is desired and then what TPI is best suited for the application

Table 5 will be helpful in visualizing the corresponding circular pitches for the different number of teeth per inch (TPI).

### General Purpose and Precision Knurling

For general purpose knurling, only limited dimensions are necessary, as shown in Fig. 6. The TPI for straight knurling is shown in Fig. 2 and the normal TPI to be specified for REED-RICO® knurls is illustrated in Fig. 8. Omit any reference to tooth or space angles.

Table 5
TPI and Circular Pitches

for Straight, Diagonal and Diamond Knurling

Straight K	nurling	Diagonal and Diamond Knurling—30° Helix Angle					
TPI	Circular Pitch		PI per Inch)	Circular Pitch			
(Teeth per Inch)	riten	Normal	Transverse	Normal	Transverse		
12	.0833	12	10.39	.0833	.0962		
16	.0625	16	13.86	.0625	.0722		
19	.0526	19	16.45	.0526	.0607		
20	.0500	20	17.32	.0500	.0577		
24	.0417	24	20.78	.0417	.0482		
25	.0400	25	21.65	.0400	.0462		
29	.0345	29	25.11	.0345	.0398		
30	.0333	30	25.98	.0333	.0385		
35	.0286	35	30.31	.0286	.0330		
40	.0250	40	34.64	.0250	.0289		
41	.0244	41	35.51	.0244	.0282		
47	.0213	47	40.70	.0213	.0246		
50	.0200	50	43.30	.0200	.0231		
80	.0125	80	69.28	.0125	.0144		




FIG. 6

In general practice, the depth of tooth of the knurling provided with REED-RICO® standard circular pitch knurls approximates the percentages of circular pitch listed.

Straight teeth - 35% of circular pitch
Diagonal teeth - 35% of normal circular
pitch


Diamond pattern:

Male - 40% of normal circular pitch Female - 25% of normal circular pitch

However, for precision straight knurling where component parts are to be fitted together, we recommend specifying only the following information. Omit any reference to tooth or space angles.

Knurled Diameter, Tooth Depth, Circular Pitch, Number of Teeth on Knurled Surface, Length of Knurled Surface

### Straight Knurling



where:

 $N_w$  = Number of teeth on work  $D_w$  = Theoretical work blank diameter p = Circular pitch

TPI = Number of teeth per inch measured on circumference of blank diameter

### Diagonal or Diamond Knurling




FIG. 8
Diagonal or Diamond Knurling —
Teeth Per Inch — TPI

$$N_w = 3.1416 \times D_w \times TPI_t$$
  
or  $3.1416 \times D_w \times TPI_n \times \cos \emptyset$ 

$$TPI_{t} = \frac{N_{w}}{3.1416 \times D_{w}}$$
 or  $TPI_{n} \times \cos \emptyset$ 

$$TPI_{n} = \frac{N_{w}}{3.1416 \times D_{w} \times \cos \emptyset} \quad or \quad \frac{TPI_{n}}{\cos \emptyset}$$

where:

N<sub>w</sub> = Number of teeth on work
D<sub>w</sub> = Theoretical work blank diameter
TPI<sub>t</sub> = Transverse teeth per inch
TPI<sub>n</sub> = Normal teeth per inch
Ø = Helix Angle (cos 30° = .86603)

TPI refers to the number of teeth per inch measured on the circumference of the work blank diameter. The approximate TPI, however, may be measured on outside diameter of the knurling for reference purposes.

For convenience in measuring the approximate TPI, the tooth pattern of the knurling may be quickly transferred to a sheet of paper. Place a piece of carbon paper (with carbon side down) on a sheet of white paper laid on a flat surface, and then roll the knurled surface of the part on the carbon paper. The impression of the knurled pattern will be transferred to the white paper for approximate measurements.

Knurled diameters and the circular pitch of the knurl are related. The circumference of the work blank should be an approximate multiple of the circular pitch for straight knurling and transverse circular pitch for diagonal and diamond knurling. Blank diameters vary with the circular pitch of the knurling selected, and should only be specified after the proper diameter of blank is determined by experimentation.




FIG. 9
Diagonal or Diamond Knurling —
Circular Pitch

$$N_{w} = \frac{3.1416 \times D_{w}}{P_{t}} \text{ or } \frac{3.1416 \times D_{w} \times \cos \emptyset}{P_{n}}$$

$$D_{w} = \frac{P_{t} \times N}{3.1416} \frac{\text{ or } P_{n} \times N_{w}}{3.1416 \times \cos \emptyset}$$

where:

 $N_{rr} = Number of teeth on work$ 

 $D_{yy}$  = Theoretical work blank diameter

P = Transverse circular pitch

P = Normal circular pitch

 $\emptyset$  = Helix angle (cos 30° = .86603)

### **Knurled Diameters**

The approximate increase in blank diameters when using REED-RICO® knurls for different teeth per inch with straight, diagonal and diamond pattern knurling is shown in Table 6. The amount of increase shown is based on knurling soft steels and should be used as a guide only. The amount of increase varies slightly with different materials.

Table 6
Approximate Increase of Blank Diameters
with Standard Reed Circular Pitch Knurls

on Soft Steels

*Teeth	Straight and	**Diamond Knurling				
per Inch	Diagonal** Knurling	Maie (Raised Points)	Female (Depressed Points)			
12	.034	.038	.023			
16	.025	.029	.017			
20	.020	.023	.014			
25	.016	.018	.011			
30	.013	.015	.009			
35	.011	.013	.008			
40	.009	.010	.007			
50	.009	.010	.007			
80	.005	.006	.004			

Refers to normal teeth per inch on diagonal and diamond knurling.

When the knurling to be produced does not require displacing sufficient material to fill the whole depth of the teeth on the knurl, it is usually necessary for the knurl to penetrate the work blank to a depth that will displace enough material too fill at least 75% of the knurl tooth depth to insure proper tracking of the knurl on the work.

Care should be exercised not to specify knurled diameters with too few teeth. Consideration should also be given to the length of the knurling and the pressure required to force the knurl into the work. The greatest pressures are exerted by the coarser pitches and with in-feed knurling using single knurls. Wide knurls require more pressure than narrow knurls. The following tabulation may be used as a guide in selecting the smallest knurled diameters to use for knurling with different number of teeth per inch (TPI) and widths of knurl faces.

\* Suggested Minimum Knurled Diameters
For In-feed Rolling with Circular Pitch Knurls on
General Applications

**TPI	Standard Width of Knurl Face						
(Teetb per Inch)	3/16	1/4	3/8				
16	5.:	13/ <sub>52</sub>	1/2				
20	5/16	11/ <sub>52</sub>	7/16				
25	1/4	952	3/8				
30	7/4	174	5/16				
35	3/16	1752	9/32				
40	5/22	\$/16	1/4				
50	1/8	5/22	7/52				
80	5/64	7/64	11/64				

Based on rolling conditions satisfactory for knurling and work being rigid and properly supported.

### **Knurling Tolerances**

For general purpose knurling of good quality, the limits and tolerances of the knurled diameters are relatively unimportant and are not specified. However, where it is necessary to specify tolerances and limits on knurled diameters for general purpose knurling, the tolerances may be expressed as 30 to 50% of the circular pitch with about 75% of the tolerances in a minus direction. Use as liberal a tolerance as possible, keeping low manufacturing cost in mind. For precision straight knurling where

<sup>\*\*</sup> With 30° belix angle.

<sup>\*\*</sup> Refers to normal TPI on diagonal knurling.

component parts are to fit together, the tolerances may be reduced to approximately 15 to 20% of the circular pitch of the knurling and the tolerance should be in the minus direction.

### **Work Blank Diameters**

Since the knurls penetrate and re-form the surface of the blank, they do not remove or compress material. The material is simply squeezed out of the roots of the part and is formed up into the crests, resulting in an increase in outside diameter. It is important, therefore, that the work blank does not contain more than the correct amount of material required to form the finished knurled diameter. Otherwise, the knurls will become overloaded and excess pressures will be exerted on both the tools and equipment if attempts are made to reduce oversize knurled diameters when too large blanks are used. The knurled diameter is larger than the unknurled blank by an amount approximately equal to the tooth depth of the knurl used. Blank diameters for knurling are therefore approximately equal to the knurled diameter minus the depth of tooth. As variation in the blank diameter results in variation of knurled diameter, it is necessary that the blank diameter tolerances be controlled according to the accuracy of the knurling to be produced. Uniformity of blanks is required to produce uniform knurling. The diameter of the blank has a definite relation to the proper tracking of the knurl on its original contact with the work. The circumference of the work blank should be an approximate multiple of the circular pitch of straight knurls and the transverse circular pitch of diagonal knurls. With improper blank diameters, the teeth of the knurl as they continue to feed into the work fail to mesh with the indentations made during the first revolution of the blank. Blanks for all knurling should be free of taper and the surface of the blank reasonably smooth. Blank diameters also differ with knurling conditions such as materials and variations of practice. Improper and varying blank diameters result in reduced knurl life, poor finish, double teeth, uneven tooth profile, and inability to obtain uniformity of number of teeth and knurled diameter on the work.

With these variations possible, it will be

readily appreciated that special attention must be given to careful preparation of blanks and to make sure the blank diameter is kept consistent with the predetermined size.

There are many variations entering into the knurling that make it difficult to establish a formula that will accurately predetermine exact blank diameters. The following formulae may be used, however, for determining a theoretical work blank diameter, or obtaining the circular pitch and number of teeth that may be rolled on a blank of a specified diameter. This applies to in-feed and end-feed knurling.

$$D_{w} = \frac{p \times N_{w}}{3.1416}$$

$$N_{w} = \frac{3.1416 \times D_{w}}{p}$$

$$p = \frac{3.1416 \times D_{w}}{N_{w}}$$

where:

D<sub>w</sub> = Theoretical work blank diameter
 N<sub>w</sub> = Number of teeth on work
 p = Circular pitch on work blank diameter for straight knurling. The transverse circular pitch is used for diagonal and diamond knurling.

Please note that the transverse circular pitch should be used when computing the number of teeth on the work blank with diagonal and diamond knurling.

TPI may be translated into circular pitch by referring to Table 5. Use standard REED-RICO® stock knurls wherever possible, as they are less expensive than special knurls and also available for immediate delivery.

The tolerances for work blank diameters vary with the knurling requirements. For general purpose knurling the tolerances usually range between 5 to 8% of the circular pitch, and for precise knurling, approximately 2 to 4% of the circular pitch.

The illustrations of sample knurling will assist in the selection of the TPI that can be obtained with standard REED-RICO® stock knurls. Special attention should be given to the suggested minimum diameters that should be used for various TPI as shown in Table 7.

### **Examples**

Determine the approximate blank diameter for rolling 60 straight teeth on a knurled surface with a 20 TPI knurl.

$$D_{w} = \frac{p \times N_{w}}{3.1416} = \frac{.0500 \times 60}{3.1416} = .955 \text{ approx.}$$
 blank diameter

where:

p = .0500 (circular pitch for 20 TPI from Table 5)

Determine the approximate number of diagonal teeth that can be rolled on a blank .625" diameter with a 30 normal TPI knurl having 30° helix angle.

$$N_{\rm w} = \frac{3.1416 \times D_{\rm w}}{p} = \frac{3.1416 \times .625}{.0385} = 51 \text{ teeth}$$

where:

p = .0385 (transverse circular pitch for 30 TPI from Table 5)

Approximate theoretical blank diameters for different TPI and number of straight teeth on the work are given in Table 8.

A proportional formula frequently used for selecting the diameter and number of teeth on a knurl to produce a specified number of teeth on a given work blank diameter is also shown.

$$\frac{D_{w}}{N_{w}} = \frac{D_{k}}{N_{k}}$$

where:

D = Diameter of the work blank

 $N_{w}$  = Number of teeth on the work blank

 $D_k$  = Outside diameter of the knurl

 $N_k = Number of teeth on the knurl$ 

Table 8
Theoretical Blank Diameters for Straight Tooth Knurling (continued on next page)

No. of Teeth on Knurled Circumference	Teeth per Inch								
No. o on K Circun	16	20	25	30	35	40	50	80	
*15 16 17 18 19						 .143 .151	.096 .102 .108 .115 .121	.060 .064 .068 .072 .076	
20 21 22 23 24	.418 .438 .458 .478	.334 .350 .366 .382	.267 .280 .293 .306	.212 .223 .233 .244 .255	.182 .191 .200 .209 .218	.159 .167 .175 .183 .191	.127 .134 .140 .146 .153	.080 .084 .088 .092 .096	
25 26 27 28 29	.497 .517 .537 .557 .577	.398 .414 .430 .446 .461	.318 .331 .344 .356 .369	.265 .276 .287 .297 .308	.227 .236 .246 .255 .264	.199 .207 .215 .223 .231	.159 .166 .172 .178 .185	.100 .104 .107 .111 .115	
30 31 32 33 34	.597 .617 .637 .657 .676	.477 .493 .509 .525 .541	.382 .395 .407 .420 .433	.318 .329 .340 .350 .361	.273 .282 .291 .300 .309	.239 .247 .255 .263 .271	.191 .197 .204 .210 .216	.119 .123 .127 .131 .135	
35 36 37 38 39	.696 .716 .736 .756 .776	.557 .573 .589 .605 .621	.446 .458 .471 .484 .496	.371 .382 .393 .403 .414	.318 .327 .337 .346 .355	.279 .287 .294 .302 .310	.223 .229 .236 .242 .248	.139 .143 .147 .151 .155	
40 41 42 43 44	.796 .816 .836 .855 .875	.636 .652 .668 .684 .700	.509 .522 .535 .547 .560	.424 .435 .446 .456 .467	.364 .373 .382 .391 .400	.318 .326 .334 .342 .350	.255 .261 .267 .274 .280	.159 .163 .167 .171 .175	
45 46 47 48 49	.895 .915 .935 .955 .975	.716 .732 .748 .764 .780	.573 .586 .598 .611 .624	.477 .488 .499 .509	.409 .418 .427 .437 .446	.358 .366 .374 .382 .390	.287 .293 .299 .305 .312	.179 .183 .187 .191 .195	
50 51 52 53 54	.995 1.015 1.035 1.054 1.074	.796 .812 .828 .843 .859	.637 .649 .662 .675 .687	.531 .541 .552 .562 .573	.455 .464 .473 .482 .491	.398 .406 .414 .422 .430	.318 .325 .331 .337 .344	.199 .203 .207 .211 .215	
55 56 57 58 59	1.094 1.114 1.134 1.154 1.174	.891 .907 .923	.700 .713 .726 .738 .751	.584 .594 .605 .615	.509 .518 .528	.446	.350 .357 .363 .369 .376	.219 .223 .227 .231 .235	
60 61 62 63 64	1.194 1.214 1.233 1.253 1.273	.971 .987 1.003	.764 .777 .789 .802 .815	.647 .658 .668	.555 .564 .573	.485 .493 .501	.382 .388 .395 .401 .407	.239 .243 .247 .251 .255	
65 66 67 68 69	1.293 1.313 1.333 1.353 1.373	1.050	.853 .866	.700 .711 .722	.600 .609	.525 .533 .541	.427	.259 .263 .267 .271 .275	
70 71 72 73 74	1.39 1.41 1.43 1.45 1.47	3   1.130 2   1.146 2   1.162	.92	.75	646	.569 .573 .581	.452 .458 .465	.279 .283 .287 .291 .294	

ا ةِ ج								
Knurled umference				Teeth p	er Inch			
No. or on Kn Circum	16	20	25	30	35	40	50	80
75	1.492	1.194	.955	.796	.682	.597	.478	.298
76	1.512	1.210	.967	.806	.691	.605	.484	.302
77	1.532	1.225	.980	.817	.700	.613	.490	.306
78	1.552	1.241	.993	.828	.709	.621	.497	.310
79	1.572	1.257	1.006	.838	.718	.629	.503	.314
80	1.592	1.273	1.018	.849	.728	.637	.509	.318
81	1.611	1.289	1.031	.859	.737	.645	.516	.322
82	1.631	1.305	1.044	.870	.746	.653	.522	.326
83	1.651	1.321	1.057	.881	.755	.660	.528	.330
84	1.671	1.337	1.069	.891	.764	.668	.535	.334
85	1.691	1.353	1.082	.902	.773	.676	.541	.338
86	1.711	1.369	1.095	.913	.782	.684	.548	.342
87	1.731	1.385	1.108	.923	.791	.692	.554	.346
88	1.751	1.400	1.120	.934	.800	.700	.560	.350
89	1.771	1.416	1.133	.944	.809	.708	.567	.354
90	1.791	1.432	1.146	.955	.818	.716	.573	.358
91	1.810	1.448	1.158	.966	.828	.724	.579	.362
92	1.830	1.464	1.171	.976	.837	.732	.586	.366
93	1.850	1.480	1.184	.987	.846	.740	.592	.370
94	1.870	1.496	1.197	.997	.855	.748	.598	.374
95	1.890	1.512	1.209	1.008	.864	.756	.605	.378
96	1.910	1.528	1.222	1.019	.873	.764	.611	.382
97	1.930	1.544	1.235	1.029	.882	.772	.618	.386
98	1.950	1.560	1.248	1.040	.891	.780	.624	.390
99	1.970	1.576	1.260	1.050	.900	.788	.630	.394
100 101 102 103 104	1.989 2.009	1.591 1.607 1.623 1.639 1.655	1.273 1.286 1.298 1.311 1.324	1.061 1.072 1.082 1.093 1.103	.909 .918 .928 .937 .946	.796 .804 .812 .820 .828	.637 .643 .649 .656 .662	.398 .402 .406 .410 .414
105		1.671	1.336	1.114	.955	.836	.668	.418
106		1.687	1.349	1.125	.964	.843	.675	.422
107		1.703	1.362	1.135	.973	.851	.681	.426
108		1.719	1.375	1.146	.982	.859	.688	.430
109		1.735	1.388	1.157	.991	.867	.694	.434
110		1.751	1.400	1.167	1.000	.875	.700	.438
111		1.767	1.413	1.178	1.009	.883	.707	.442
112		1.782	1.426	1.188	1.019	.891	.713	.446
113		1.798	1.438	1.199	1.028	.899	.719	.450
114		1.814	1.451	1.210	1.037	.907	.726	.454
115		1.830	1.464	1.220	1.046	.915	.732	.458
116		1.846	1.477	1.231	1.055	.923	.739	.462
117		1.862	1.489	1.241	1.064	.931	.745	.466
118		1.878	1.502	1.252	1.073	.939	.751	.470
119		1.894	1.515	1.263	1.082	.947	.758	.474
120 121 122 123 124		1.910 1.926 1.942 1.957 1.973	1.540 1.553 1.566	1.284 1.294 1.305	1.091 1.100 1.110 1.119 1.128	.955 .963 .971 .979 .987	.764 .770 .777 .783 .789	.478 .482 .485 .489 .493
125 126 127 128 129		1.989 2.005 2.021 2.037 2.053	1.604 1.617 1.629	1.348	1.137 1.146 1.155 1.164 1.173	.995 1.003 1.011 1.019 1.027	.796 .802 .809 .815 .821	.497 .501 .505 .509 .513

<sup>\*</sup>Refer inquiries for less than 15 teeth to REED-RICO\*.

# Table 8 (cont.)


No. of Teeth on Knurled Circumference				Teeth	per Inch	· • • • • • • • • • • • • • • • • • • •		
No. 6 Circui	16	20	25	30	35	40	50	80
130 131 132 133 134		2.069 2.085 2.101	1.655 1.668 1.680 1.693 1.706	1.379 1.390 1.401 1.411 1.422	1.182 1.191 1.200 1.210 1.219	1.034 1.042 1.050 1.058 1.066	.828 .834 .840 .847 .853	.517 .521 .525 .529 .533
135 136 137 138 139			1.719 1.731 1.744 1.757 1.769	1.432 1.443 1.454 1.464 1.475	1.228 1.237 1.246 1.255 1.264	1.074 1.082 1.090 1.098 1.106	.859 .866 .872 .879 .885	.537 .541 .545 .549 .553
140 141 142 143 144			1.782 1.795 1.808 1.820 1.833	1.485 1.496 1.507 1.517 1.528	1.273 1 282 1.291 1 300 1.310	1.114 1.122 1.130 1.138 1.146	.891 .898 .904 .910 .917	.557 .561 .565 .569 .573
145 146 147 148 149			1.846 1.859 1.871 1.884 1.897	1.539 1.549 1.560 1.570 1.581	1.319 1.328 1.337 1.346 1.355	1.154 1.162 1.170 1.178 1.186	.923 .929 .936 .942 .949	.577 .581 .585 .589 .593
150 151 152 153 154			1.909 1.922 1.935 1.948 1.960	1.592 1.602 1.613 1.623 1.634	1 364 1 373 1 382 1 391 1 401	1.194 1 202 1.210 1.217 1.225	.955 .961 .968 .974 .980	.597 .601 .605 .609 .613
155 156 157 158 159	 		1.973 1.986 1.999 2.011 2.024	1.645 1.655 1.666 1.676 1.687	1.410 1.419 1.428 1.437 1.446	1.233 1.241 1.249 1.257 1.265	987 .993 1.000 1.006 1.012	.617 .621 .625 .629 .633
160 161 162 163 164	•••		2.037 2.049 2.062 2.075 2.088	1.698 1.708 1.719 1.729 1.740	1.455 1.464 1.473 1.482 1.491	1.273 1.281 1.289 1.297 1.305	1.019 1.025 1.031 1.038 1.044	.637 .641 .645 .649 .653
165 166 167 168 169			2.100 2.113	1.751 1.761 1.772 1.783 1.793	1.501 1.510 1.519 1.528 1.537	1.313 1.321 1.329 1.337 1.345	1.050 1.057 1.063 1.070 1.076	.657 .661 .665 .669 .673
170 171 172 173 174				1.804 1.814 1.825 1.836 1.846	1.546 1.555 1.564 1.573 1.582	1.353 1.361 1.369 1.377 1.385	1.082 1.089 1.095 1.101 1.108	.676 .680 .684 .688 .692
175 176 177 178 179				1.857 1.867 1.877 1.889 1.899	1.592 1.601 1.610 1.619 1.628	1.393 1.400 1.408 1.416 1.424	1.114 1.120 1.127 1.133 1.140	.696 .700 .704 .708 .712
180 181 182 183 184				1.910 1.920 1.931 1.942 1.952	1.637 1.646 1.655 1.664 1.673	1.432 1.440 1.448 1.456 1.464	1.146 1.152 1.159 1.165 1.171	.716 .720 .724 .728 .732
185 186 187 188 189				1.963 1.974 1.984 1.995 2.005	1.682 1.692 1.701 1.710 1.719	1.472 1.480 1.488 1.496 1.504	1.178 1.184 1.190 1.197 1.203	.736 740 .744 .748 .752


### Dimensioning of Circular Pitch Knurling

Uniform drafting practice is desirable and dimensioning should include length and knurled diameter of the knurling and specifications of the teeth. The method of dimensioning diameters and tooth specifications is important as improper use of dimensions may result in considerable confusion.

The designer should always allow leeway in dimensioning knurled diameters so the setup person may experiment in establishing the exact relationship between the work blank diameter and the diameters on the finished knurled product. General information on blank diameters appears on page 10. Approximate amounts to add to the blank diameters to obtain the knurled diameters for different TPI and types of knurling are given in Table 6.

Allowance for variation in number of teeth in the knurled diameter should also be made unless the use of the knurled surface demands an exact number of teeth made to a prescribed form. In such cases, precise limits on blank diameters will be required and these limits can only be determined by experimentation with precision made knurls for the specific material and work to be knurled.








FIG. 10

# Diametral Pitch Knurling

An American Standard ANSI/ASME B94.6-1984 has been issued for diametral pitch knurling and has been designed on the basis of diametral pitch instead of the commonly used circular pitch and TPI (teeth per inch) system. Diametral pitch knurling has been developed for work blank diameters that are standard fractional stock sizes in multiples of 1/64" or 1/32" depending upon the diametral pitch selected. The fractional blank diameter sizes apply to straight and diagonal knurling for both in-feed and end-feed knurling. End-feeding for diagonal knurling with the axes of straight knurls set over at a specified helix angle usually requires decimal size blank diameters as described on page 17.

### Standard Diametral Pitches

The four standard diametral pitches available are 64, 96, 128 and 160. The 96 and 160 diametral pitches are for blank diameters having fractional increments of 1/32" and the 64 and 128 diametral pitches are for blank diameters having fractional increments of 1/64". The American Standard recommends that the use of the 64 diametral pitch should be avoided as much as possible, and for simplification of tools, preference be given to the use of 96 diametral pitch.

The term diametral pitch applies to the quotient of the total number of teeth in the circumference of the work divided by the basic diameter of the work blank. The diametral pitch is the ratio of the number of teeth on the work to the number of inches of basic work blank diameter and equals the number of teeth to each inch of basic blank diameter.

$$p = \frac{N_w}{D_w}$$

where:

p = Diametral pitch

 $N_w$  = Number of teeth on the work, or p x  $D_w$  = Theoretical work blank diameter, or  $N_w$ 

The diametral pitch and the number of teeth are always measured in a transverse plane which is perpendicular to the axis of rotation for diagonal as well as straight knurling as illustrated

in Fig. 9.

A comparison of diametral pitches, TPI and circular pitches is shown in Table 9.

Diagonal and diamond knurling on work blank may be accomplished by setting the axes of straight knurls at an angle to the work axis as shown in Fig. 11.

When using straight knurls to produce diagonal and diamond knurling by end-feeding, the transverse diametral pitch that is produced on the work will not be the same as that of the knurl. The diametral pitch in such instances refers to the diametral pitch on the knurl rather than the knurling produced on the work.

Table 9

Approximate Increase of Blank Diameter
Straight & Diagonal American Standard
ANSI/ASME B94.6—1984

	Inch		Approx. of Too Incres Knu Dian	oth or use in irled	f Teeth nce	Work Diam	
Diametral Pitch	**Teeth per Approx.	**Circular Pitch	Straight	Diagonal	Min. No. of Te in Knurled Circumference	Range	Diameter Increments
64 96 128 160	20.4 30.6 40.7 50.9	.0491 .0327 .0245 .0196	.024 .016 .012 .009	.021 .014 .010 .008	24 24 18 15	3/8-1 1/4-1 9/4-1 3/2-1	1/81/82 1/81/8 1/81/8 1/81/8 1/81/8 1/81/8 1/8

Refers to transverse TPI and transverse circular pitch on diagonal knurling.

### **Knurling Tolerances**

The American Standard ANSI/ASME B94.6-1984 for straight and diagonal knurling applies to work blank diameters up to 1" as shown in Table 10, which includes three classes of tolerances. These classes and recommended applications are as follows:

Class I. Tolerances in this classification may be applied to straight, diagonal and raised diamond knurling where the knurled outside diameter of the work need not be held to close dimensional tolerances. Such applications include knurling for decorative effect, grip on thumbscrews, and inserts for moldings and castings.

**Class II.** Tolerances in this classification may be applied to straight knurling only and are recommended for applications requiring closer dimensional control of the knurled outside diameter than provided for by Class I tolerances.

**Class III.** Tolerances in this classification may be applied to straight knurling only and are recommended for applications requiring closest possible dimensional control of the knurled outside diameter. Such applications include knurling for close fits.

### **Work Blank Diameters**

The fractional and decimal sizes of the work blank up to 1" diameter for in-feed knurling are shown in Table 10. The formulae for theoretical work blank diameters are as follows:

$$D_{w} = \frac{N_{w}}{p}$$

where:

D<sub>w</sub> = Theoretical work blank diameter

 $N_{w} = Number of teeth on the work$ 

p = Diametral pitch

The theoretical work blank diameters up to 1" for end-feed diagonal and diamond knurling with straight tooth knurls are shown in Table 11 for helix angle of 30°.

For end-feed knurling with straight tooth

$$D_{w} = \frac{N_{w}}{p \times \cos \Psi}$$


where:

D<sub>w</sub> = Theoretical work blank diameter

 $N_w$  = Number of teeth on the work measured in transverse plane

p = Diametral pitch on knurl

 $\Psi$  = Angle between knurl axis and work axis (cos 30° = .86603)



The number of teeth produced on the work blank is measured in the transverse plane and may be determined with the following formula for diagonal knurling.

$$N_w = D_w x p x \cos \psi$$
  
where:

 $N_w$  = Number of teeth produced on the work blank measured in the transverse plane

D. = Diameter of work blank

p = Diametral pitch on knurl

 $\psi$  = Angle between knurl axis and work axis **For Example:** If 30° diagonal knurling were to be produced on 1" stock with a 96 diametral pitch straight knurl.

 $N_w = 1.000 \times 96 \times .86603 = 83.14 \text{ teeth}$ Note: .86603 equals cosine of 30°.

Increasing the angle between the knurl axis and the work axis to approximately 30 1/4° would provide good tracking of the knurl and make it possible to obtain an even 83 teeth instead of 83.14.

By reducing the diameter of the work blank to a decimal size, good tracking of the knurl can be obtained for 30° diagonal knurling according to the following formula:


$$D_w = \frac{N_w}{p \times \cos \psi} = \frac{83}{96 \times .86603} = .998 \text{ inch}$$

The tolerances for work blank diameters vary with the knurling requirements. For general purpose knurling the tolerances usually range between 5 to 8% of the circular pitch and for precise knurling, approximately 2 to 4% of the circular pitch.

### **Dimensioning of Diametral Pitch Knurling**

Uniform drafting practice is desirable and dimensioning should include length and knurled diameter of the knurling and specifications of the teeth. The method of dimensioning diameters and tooth specifications is important as improper use of dimensions may result in considerable confusion.

Always specify the tooth pattern of the knurling, stating whether it is straight, diagonal or diamond pattern (male or female). Mention whether the diagonal knurling is right or left hand, and indicate the angle of the helix.



# Table 10

# Data for Fractional Blank Diameters - In-feed Knurling

Using Straight and Diagonal Diametral Pitch Knurls for Blank Diameters up to One Inch ANSI/ASME B94.6-1984

	ca Divers	ral Pitch*	96 Diametr	al Pitch*	128 Diamet	tral Pitch	160 Diametr	
Diameter of Blank	Knurled Diameter	No. of Teeth in	Knurled Diameter	No. of Teeth in Knurled	Knurled Diameter	No. of Teeth in Knurled Circum.	Knurled Diameter	No. of Teeth in Knurled Circum.
		Circum.		Circum.			0.103 0.134	15 <b>20</b>
340.094		:::				18		żś
36 0.141	:::	•••		:::	0.153 0.168	20 1 1	0.165	•••
54	:::	:::			0.184	22	0.197	30
0 188	•••			•••	0.200 0.215	24 26 28	0.228	35
76 0.203	:::	::: 1	:::	:::	0.231 0.246	28 30	0.259	40
154 0.234	•••	:::	0.266	24	0.262	32	V.23	
174 0.266	•••				0.278	34 26	0.290	45
%0.281 F	•••		0.297	27	0.293 0.309	36 38	0.321	ŠÖ
13/4 0.297	•••	:::	0.328	30	0.324 0.340	40 42	:::	***
21/4 0.328		***	0.360	33	0.356	44	0.353	\$\$ • • • •
11/4 0.344 12/4 0.359		:::	!	36	0.371 0.387	46 48	0.384	60
3/4	0.399 0.414	24 25	0.391	- 1	0.403	50 52	0.415	65
<sup>25</sup> ⁄ <sub>4</sub> 0.391 13∕ <sub>4</sub> 0.406	0.430	26	0.422	39	0.418	: :	.:::-	70
7/4 0.422	0.446 0.462	27 28 29 30	0.454	42	0.434 .0.450	54 56 58	0.447	
7/6 0.438 29/4 0.453	0.477	29	0.485	45	0.465 0.481	1 60 I	0.478	75
1542 -0.469 3144 .0.484	0.493 0.508	30	0.403		0.496	62	0.509	80
0.500	0.524	32	0.516	48	0.512 0.528	64 66 68 70 72	0.540	
** 38Z 0.516	0.540 0.555	33 34	0.547	;;	0.543	68	1	1
174 0.531 354 0.547	0.571	35 36	0.578	54	0.559 0.574	72	0.571	90
0.562	0 586	37			0.590	74	0.603	95
<sup>3</sup> / <sub>4</sub> 0.578 19/ <sub>2</sub> − 0.594	0.602 0.618	38 39	0.610	57	0.606 0.621	76 78	0.634	100
3%4 0.609 5% 0.625	0.633	40	0.641	60	0.637 0.653	80 82	0.00	:::
41/4 0.641	0.665	41			0.668	84	0.665	105
21/2 0.656 45/4 0.672	0.680 0.696	42 43	0.672	63	0.684	86 88	0.697	iio
1140.688	0.712	44 45	0.704	66	0.700 0.715	90	0.728	iiš
2/4 0.703 2/4 0.719	0.727 0.743	46	0.735	69	0.731	92	1	
€ 0.734	0.758	47	0.766	72	0.746 0.762	94 96	0.759	120
3/4 0.750 9/4 0.766	0.774 0.790	48 49		1	0.778 0.793	98 100	0.790	iżś
25/4 0.781 51/4 0.797	0.805 0.821	50 51	0.797	75	0.809	102		1 :::
	0.836	1 1	0.828	78	0.824	104 106	0.821	130
× 5 0.828	0.852	53	0.860	81	0.840 0.856	108	0.833	135
35/4 0.859	0.883	52 53 54 55 56	0.891	84	0.871 0.887	110 112	0.884	140
<del>3/80.875</del>			0.071	-	0.903	114		iäs
574 0.891 294 0.906	II 0.930	57 58 59	0.922	87	0.918	116 118	0.915	l
3% 0.922	0.946	60	0.954	90	0.950 0.965	120 122	0.947	150
15/6 0.938 61/4 0.953		61		•••	0.981	124	0.978	155
31/4-0.969	0.993 1.008	62 63	0.985	93	0.996	126 128	1,009	160
1 1.000		64	1.016	96	1.012		1 1	+0.002
	Class	+0.005		+0.004 -0.010	1::::		11::::	-0.006
Recommended Tolerance on	1	-0.012	1	10.000	1	<b>∔0.000</b>	11	+0.000
Knurled	Class II	+0.000 -0.010	1::::			-0.008	1	-0.006
Outside Diameters	Class	+0.000	1	+0.000				0 003
	iii	-0.006	<del>  · · · ·</del>		<del></del>		† <del>  ```</del>	
	Classes			10.001		±0.0007	'	10.0005
Recommended Tolerance on	1 & 11		1	+0.000	1	±0.0000	ol I	
Work Blank Diamete		+0.0000 -0.0015	1	-0.001	1	-0.000		0.000
Before Knurling (1	.)   111	-0.0013	1		l			

<sup>\*</sup> USE OF 64 DIAMETRAL PITCH KNURL should be avoided as much as possible. For simplification of tools it is recommended that preference be given to use of 96 Diametral Pitch shown in italics.

<sup>(1)</sup> Recommended tolerance on Class I and II work blanks is equal to 6% of the circular pitch on the nominal diameter. Recommended tolerance on Class III work blanks is equal to 3% of the circular pitch on the nominal diameter.

For unlisted diameters refer to formulas on Page 15.

# Table 11

# \* Theoretical Blank Diameters for Diagonal and Diamond Knurling - End-feed Knurling - with Straight Knurls

Produced by Straight Diametral Pitch Knurls with 30° Angle Between Axis of Work and Knurl Axis and for Blank Diameters up to One Inch

ANSI/ASME B94.6-1984

of Teeth n Work	]	Diametra	al Pitch		o. of Teeth		Diametr	al Pitch		of Teeth n Work		Diamet	ral Pitch	
No. of	†64	÷96	128	160	No. of	†64	†96	128	160	No. of	†64	†96	128	160
15 16 17			0.153	0.108 0.115 0.123	57 58 59		0.686 0.698 0.710	0.514 0.523 0.532	0.411 0.419 0.426	98 99			0.884 0.893	0.707 0.714
18 19 20			0.162 0.171 0.180	0.130 0.137 0.144	60 61 62	•••	0.722 0.734 0.746	0.541 0.550 0.559	0.433 0.440 0.447	100 101 102 103			0.902 0.911 0.920 0.929	0.722 0.729 0.736 0.743
21 22 23 24	0.397 0.415 0.433	0.265 0.277 0.289	0.189 0.198 0.207 0.217	0.152 0.159 0.166 0.173	63 64	•••	0.758 0.770	0.568 0.577	0.455 0.462	104	• • • •		0.938	0.751
25 26 27 28	0.451 0.469 0.487 0.505	0.301 0.313 0.325 0.337	0.226 0.235 0.244 0.253	0.180 0.188 0.195 0.202	65 66 67 68 69		0.782 0.794 0.806 0.818 0.830	0.586 0.595 0.604 0.613 0.622	0.469 0.476 0.484 0.491 0.498	106 107 108 109		•••	0.956 0.965 0.974 0.983	0.765 0.772 0.779 0.787
30 31 32	0.523 0.541 0.559 0.577	0.349 0.361 0.373 0.385	0.262 0.271 0.280 0.289	0.209 0.217 0.224 0.231	70 71 72 73 74		0.842 0.854 0.866 0.878 0.890	0.631 0.640 0.650 0.659 0.668	0.505 0.512 0.520 0.527 0.534	110 111 112 113 114			0.992 1.001 	0.794 0.801 0.808 0.815 0.823
33 34 35	0.595 0.613 0.631	0.397 0.409 0.421	0.298 0.307 0.316	0.238 0.245 0.253	75 76		0.902 0.914	0.677 0.686	0.541 0.548	115 116 117				0.830 0.837 0.844
36 37 38 39	0.649 0.667 0.685 0.703	0.433 0.445 0.457 0.469	0.325 0.334 0.343 0.352	0.260 0.267 0.274 0.281	77 78 79		0.926 0.938 0.950	0.695 0.704 0.713	0.556 0.563 0.570	118 119 120	•••			0.852 0.859 0.866
40 41 42 43	0.721 0.740 0.758 0.776	0.481 0.493 0.505 0.517	0.361 0.370 0.379 0.388	0.289 0.296 0.303 0.310	80 81 82 83 84		0.962 0.974 0.986 0.998 1.010	0.722 0.731 0.740 0.749 0.758	0.577 0.585 0.592 0.599 0.606	121 122 123 124				0.873 0.880 0.888 0.895
44 45 46 47 48	0.794 0.812 0.830 0.848 0.866	0.529 0.541 0.553 0.565 0.577	0.397 0.406 0.415 0.424 0.433	0.318 0.325 0.332 0.339 0.346	85 86 87 88 89			0.767 0.776 0.785 0.794 0.803	0.613 0.621 0.628 0.635 0.642	125 126 127 128 129				0.902 0.909 0.917 0.924 0.931
50 51 52 53	0.884 0.902 0.920 0.938 0.956	0.589 0.601 0.613 0.625 0.637	0.442 0.451 0.460 0.469 0.478	0.354 0.361 0.368 0.375 0.382	90 91 92 93 94			0.812 0.821 0.830 0.839 0.848	0.650 0.657 0.664 0.671 0.678	130 131 132 133 134				0.938 0.945 0.953 0.960 0.967
54 55 56	0.974 0.992 1.010	0.650 0.662 0.674	0.487 0.496 0.505	0.390 0.397 0.404	95 96 97	• • •		0.857 0.866 0.875	0.686 0.693 0.700	135 136 137 138				0.974 0.981 0.989 0.996

<sup>\*</sup> Modification of these diameters may be made in order to suit various knurling conditions such as materials and variations in practice. † USE OF 64 DIAMETRAL PITCH KNURL should be avoided as much as possible. For simplification of tools it is recommended that preference be given to use of 96 Diametral Pitch shown in italics.

# Knurling on Screw Machines and Lathes

### **Knurling with Cross Slide Holders**

Straight or diamond knurling can be produced by using either one or two knurls mounted in a holder on the cross slide. When so used, straight knurls are limited to straight knurling. Only one diamond pattern knurl can be used for diamond knurling, whereas two diagonal knurls of opposite hands will produce a male diamond pattern on the work. Where tooling setup provides space for two knurls, the combination of right and left diagonal knurls will produce a cleaner male diamond pattern that can be obtained with a single female diamond knurl. Diamond knurls require greater pressure than straight or diagonal knurls and sometimes place prohibitive loads on both machine and work. Only a male diamond knurl, however, can produce a female diamond impression.

Knurls may be mounted on the front or rear cross slides. Various designs of knurl holders are available. The knurls in the single knurl holders usually exert direct pressure against the work and the diameter of the knurling is controlled by the size of the blank and the final positioning of the cross slide. Single knurl holders usually occupy minimum tool space and are also made for use in combination with holders for cutting operations — in such instances the knurl passes either over or under the work. Some holders have two knurls mounted in a unit which applies direct pressure to the work.

Compact adjustable floating straddle type holders with two knurls are also used on cross slides. The two opposed knurls form the knurling as they are fed on to the blank — final size of the knurling being obtained when the knurls reach the center of the work. The diameter of knurling is controlled by the size of the blank and a predetermined setting of the center distance between knurls in the holder. The cross slide travel is only used as a means of feeding the knurls to and from the work. Side pressure on the work and the machine spindle is reduced with straddle type holders as most of the pressure required for knurling is absorbed in the holder.

### **Knurling with Turret Holders**

Straight, diagonal or male diamond knurling may be produced with swing type in-feeding holders and adjustable swivel type end-feeding knurl holders mounted in the turret. Adjustment is provided in the holder for setting the knurls for the diameter of knurling desired. Knurls used for end-feeding should have beveled edges.

Only straight and diagonal knurls can be used with the end-feeding holders. When producing diagonal and diamond knurling with straight knurls, the axes of the straight knurls are swiveled in the holder for obtaining the diagonal and diamond knurling as the knurls are fed over the blank.

Straight knurling may be produced with end-feeding holders using either straight or diagonal knurls. Of these two methods, the use of diagonal knurls of the same hand is preferred. The axes of the diagonal knurls are swiveled in the holder to obtain straight knurling as the knurls are fed over the blank. This method permits easier starting of the knurls with uniform raise up of material. Since the axes of the knurls and the work are not parallel, a burnishing action occurs resulting in higher quality knurling. Continuous full contact of the knurls with the blank is maintained for control of the depth of knurling even on long work which may spring slightly away from the centerline.

Setting the axes of knurls at an angle has the disadvantage, however, of not being able to knurl close to shoulders as the leading edges of the swiveled knurls will touch the shoulder before the points of contact of the knurls with the work have reached the shoulder. When using diagonal knurls for end-feeding, it is important to have a stiff spring for returning the turret when withdrawing the knurls from the work.

Both straight and diagonal knurls are used in the swing type in-feeding holders in the turrets. The holder is in the open position as the turret brings the knurl, or knurls, over the work and the cross slide is used to close the holder and engage the knurls with the work.

### Speeds and Feeds

Knurling is ordinarily performed at the same speeds used in the cutting operations. However, where spindle speeds can be reduced without loss of production, it is recommended that spindle speeds be lowered as much as possible to increase knurl life.

For in-feed knurling, the knurl should be fed toward the work gradually until contact is made with the blank, and from there on, the feed should be progressive until the feed is at the high point of the cam. As few work revolutions as possible should be allowed for feeding the knurl into the work. The knurl should be fed to full depth as rapidly as permissible without causing undue pressure on the work, the tools and the equipment. Too many revolutions may result in a roughened or slivered tooth surface and destruction of the knurl and the knurling.

The rate of feed is governed by the kind of material being knurled, diameter and rigidity of the work, and the width and pitch of the knurl. Faster feeds are used for the softer materials and slower feeds for harder materials. Although the knurling should be normally completed within 10 to 25 work revolutions, the ability of many machine cross slides to operate at the desired high speeds prohibits the use of the preferred revolutions, especially when high work spindle speeds are used.

The cam rise must be continuous with no dwell or backing away until the high point is reached. It is desirable to have a slight dwell on the cam at the completion of the feeding which allows several revolutions of the work with the knurl at full tooth depth. The amount of dwell depends upon the nature of the work and the material. The knurl should be then withdrawn from the work quickly.

The feeds used for end-feed knurling with the turret vary considerably and are dependent upon the pitch of the knurl, material being knurled and the nature and diameter of the work.

Table 12 may be used as a guide for determining the amount of end-feed per revolution of the work. The rate of the feed for diamond pattern knurling is slower than that for straight or diagonal knurling.

Table 12
Turret Knurling Straight or Diagonal
Approximate End-feed per Revolution of Work

		Material								
TPI	Brass	Steel 10-25 Carbon	Steel 30-50 Carbon or Alloy							
16-20 25-35 40-80	.010 .013 .017	.006 .008 .010	.004 .005 .006							

# Table 13 Bump Knurling

Approximate In-feed (cross-slide) per Revolution of Work

	General App	lication
TPI	Feed/Rev.	Approximate* Minimum Blank Dia.
16-20	.002	3/8"
25-35	.001	1/4"
40-80	.0006	1/8"

<sup>\*</sup> Based on a minimum of 20 teeth on circumference of work and approximately 1/4" wide knurl.

REMEMBER: Penetration is only 1/2 of the knurl tooth depth. The

remaining 1/2 is displaced material.

# Knurling on Thread Rolling Machines

### With Reciprocating Type Machines

Flat knurling dies are used on reciprocating thread rolling machines. They may be made with either single or duplex faces. Two dies are used; one stationary, and one moving. The rolling faces of the dies are located opposite each other as shown in Fig. 13.

The knurling is rolled on the blank during the forward stroke of the machine and the number of revolutions provided for rolling the knurling is dependent upon the die length. The rate of penetration is determined by the shape of the die. Flat knurling dies are used only for in-feed knurling, and the depth of die face is usually made to suit the length of knurling required.




FIG. 13
Reciprocating Thread Rolling Machines
Using Flat Knurling Dies

### With Cylindrical Die Machines

Cylindrical knurls are used on cylindrical die thread rolling machines. These machines use two or three knurls which are mounted on parallel axes and rotate in the same direction.

On the two-die type machines, the two knurls are opposed and the blank being knurled is supported on a work rest between the knurls. The center of the blank raises from the work rest as the diameter of the blank increases during the rolling of the knurled surface. On the three-die type machines, the three knurls are equally spaced around the blank which floats between




FIG. 14
Cylindrical Die Machine — 2 Die Type




FIG. 15
Cylindrical Die Machine — 3-Die Type

them, as shown in Fig. 15.

Since knurls are circular in shape, the number of revolutions provided for knurling and the rate at which the knurls are fed into the work can be controlled by the set-up. Cylindrical die machines may be used for both in-feed and end-feed knurling.

C Se	ries	B Se	eries	S Se	ries	-	\ Se	eries	F Se	ries				
	20	3	110		20					5 20	Si	tand Stoc	D-RIO ard K cked only	nurls y in
DIA.	1/2"	DIA.	5/8"	DIA.	3/4"	DIA		3/4"	DIA.	7/8"		_	Speed S Sout bev	
WIDTH HOLE	3/16" 3/16"	WIDTH	1/4" 1/4"	WIDTH	1/4" 1/4"	HO		3/8" 1/4"	WIDTH HOLE	3/8" 1/4"			nout bev vels will	
00K,	Holders: Charpe No. (00D) (00AA) (00BA) (00CA)		Holders: Sharpe No. (200) (22DA) (20AA) (20BA) (20C)	2K,	Holders: Sharpe No. (24A) (22AA) (22BA) (22C)	Will Fit Following Holders: Brown & Sharpe No. 185-224 (24A) 190-122 (22AA) 195-122 (22BA) 200-122 (22C) 210-122 (22CKB) Armstrong No. 1K, 2K, 3K-1, 3K-2, 673, 674 All Pratt & Whitney		Holders: Sharpe No. (24A) (22AA) (22BA) (22C) (22C) (22KB) g No. 1K, 1, 3K-2, 674	Fellowing Brown & S	:6 :s 50-		whe	shed wit extra cos en specif	t
	y KT-00 L 00	Detter	beck 0		s 50-36	J. H	i. Wil , 2K, :	liams No. 3K1, 3K2			SA S	eries	Swi	ss
Slitter	s 50-34	R&L	oy KT-0 1, 2, 3 s 50-35			B: Slit	arnaby ters 5	No. 2, 3 / KT-2G 0-1, 50-2, 50-36			DIA. WIDTH HOLE	3/4" 1/2" 1/4"	DIA. WIDTH HOLE	5/16" 5/32" 1/8"
				S	TRAIG	НТ	ТО	отн к	NURLS	3				
On all t	liati	BS 12	12 T.P.I. 23 Teeth 90°			AS	12	12 T.P.L 28 Teeth 90°						
On all I ANGLE i is INCL	ndicated	BS 16	16 T.P.1 31 Teeth 90°	SS 16	16 T.P.L 38 Teeth 90°	AS	16	16 T.P.L 38 Teeth 90°						
angle o		BS 19	19 T.P.L 37 Teeth 90°	SS 19	19 T.P.I. 45 Teeth 90°									
CS 20	20 T.P.I. 31 Teeth 90°	BS 20	20 T.P.I. 39 Teeth 90°	SS 20	20 T.P.I. 47 Teeth 90°	AS	20	20 T.P.I. 47 Teeth 90°	FS 20	20 T.Pi 55 Teeth 90°	SAS 20	20 T.P.I. 47 Teeth 90°		
		BS 24	24 T.P.I. 47 Teeth 90°	SS 24	24 T.P.I. 57 Teeth 90°									
CS 25	25 T.P.I. 38 Teeth 90°	BS 25	25 T.P.I. 49 Teeth 90°	SS 25	25 T.P.I. 59 Teeth 90°	AS	25	25 T.P.I. 59 Teeth 90°	FS 25	25 T.P.1 69 Teeth 90°				
		BS 29	29 T.P.I. 56 Teeth 90°	SS 29	29 T.PI. 68 Teeth 90°			20 701		30 T.P.I.		30 TPI		
CS 30	30 T.P.1 47 Teeth 90°	BS 30	30 T.P1 59 Teeth 90°	SS 30	71 Teeth 90°	-	30	30 T.P.I. 71 Teeth 90°	FS 30	82 Teeth 90°	SAS 30	71 Teeth 90°		
CS 35	35 T.P.L 55 Teeth 90°	BS 35	68 Teeth 90° or 70° 40 T.P.I.	SS 35	82 Teeth 90°		35	82 Teeth 90°				· · · · · · · · · · · · · · · · · · ·		40 TPL
CS 40	63 Teeth 90°	BS 40	78 Teeth 90°	SS 40	94 Teeth 90°	AS	40	94 Teeth 90°					SWS 40	39 Teeth 90°
CS 41	65 Teeth 90°	BS 41	81 Teeth 90°	-										
CS 47	73 Teeth 90°	BS 47	92 Teeth 90°		50 T.P.I.			50 T.P.L					0140 50	50 TP1
CS 50	79 Teeth 70°	BS 50	98 Teeth 70°	SS 50	117 Teeth 70°	AS	50	117 Teeth 70°	-				SWS 50	49 Teeth 70°
CS 53	84 Teeth 70°						·						01115 ==	60 T.P.L
CS 60	60 T.P.I. 94 Teeth 70°		·			-							SWS 60	59 Teeth 70°
CS 70	70 T.P.I. 109 Teeth 70°		80 T.P.i.		80 T.P.I.	-		80 T.P.I.		·			SWS 70	69 Teeth 70°
CS 80	80 T.P.I. 125 Teeth 70°	BS 80	155 Teeth 70°	SS 80	189 Teeth 70°	AS	80	189 Teeth 70°					SWS 80	79 Teeth 70°

C Se	ries	B Se	ries	S Ser	ies	A Se	ries
DIA. WIDTH HOLE	1/2" 3/16" 3/16"			DIA. WIDTH HOLE	3/4" 1/4" 1/4"	DIA. WIDTH HOLE	3/4" 3/8" 1/4"

									<b>A.</b>
GONAI	LT	00	TH KN	IUR	LS	<b>— 30</b> °	SI	71K	AL
							AD ·	12R	12 T.P.I. 25 Teeth 90°
E	3D 1	6R	16 T.P.I. 27 Teeth 90°				AD	16R	16 T.Pi. 33 Teeth 90°
7 Teeth	3D 2	20R	34 Teeth	SD 2	OR		AD	20R	20 T.PJ. 41 Teeth 90°
5 T.P.L 4 Teeth	BD 2	25K	42 Teeth	SD 2	5R	25 T.P.I. 51 Teeth 90°	AD	25R	25 T.P.I. 51 Teeth 90°
O T.P.L O Teeth	BD :	30R	30 T.P.L 52 Teeth 90°	SD 3	0R	30 T.P.I. 61 Teeth 90°	AD	30R	30 TPL 61 Teeth 90°
	BD :	35R	35 T.Pi. 59 Teeth 90°				AD	35R	35 T.P.I. 71 Teeth 90°
io T.P.I. is Teeth	BD 4	40R	40 T.Pi. 68 Teeth 90°	SD 4	OR	40 T.P.L 81 Teeth 90°	AD	40R	40 T.P.I. 81 Teeth 90°
50 T.P.L 58 Teeth 70°	BD	50R	50 T.P.I. 86 Teeth 70°	SD 5	OR	50 T.P.I. 102 Teeth 70°	AD	50R	50 T.P.L 102 Teeth 70°
			· · · · · · · · · · · · · · · · · · ·		<u> </u>		AD	12L	12 T.P.I. 25 Teeth 90°
	BD	16L	16 T.P.L 27 Teeth 90°				AD	16L	16 T.P.I. 33 Teeth 90°
20 T.P.L 27 Teeth 90°	BD	20L	20 T.P.I. 34 Teeth 90°	SD 2	20L	20 T.P.I. 41 Teeth 90°	AD	20L	20 T.P.I 41 Teeth 90°
25 T.P.L 34 Teeth 90°	BD	25L	25 T.P.I. 42 Teeth 90°	SD :	25L	25 T.P.I. 51 Teeth 90°	AD	25L	25 T.P.I. 51 Teeth 90°
30 T.P.I. 40 Teeth 90°	BD	30L	30 T.P.i. 52 Teeth 90°	SD	30L	30 T.P.I. 61 Teeth 90°	AD	30L	30 T.P.I. 61 Teeth 90°
	BD	35L	35 T.P.I. 59 Teeth 90°				AD	35L	35 T.PI. 71 Teeth 90°
40 T.Pi. 55 Teeth 90°	BD	40L	40 T.Pi. 68 Teeth 90°	SD	40L	40 T.P.I. 81 Teeth 90°	AE	40L	40 T.P.1 81 Teeth 90°
50 T.P.I. 68 Teeth 70°	BD	50L	50 T.P.L 86 Teeth 70°	SD	50L	50 T.P.I. 102 Teeth 70°	AE	501	50 T.P.1 102 Teeth 70°
	O T.P.I. 7 Teeth 0° 5 T.P.I. 4 Teeth 0° 5 T.P.I. 0 Teeth 0° 10 T.P.I. 10 T.P	BD 1  OTPL 7 Teeth For Streeth OTPL 0 Teeth OTPL 0 Teeth OTPL 0 Teeth OTPL ST Teeth ST Teeth OTPL ST Teeth ST T	BD 16R  DTPL 7 Teeth 8D 25R  DTPL 0 Teeth 8D 30R  BD 35R  BD 35R  BD 40R  DTPL 55 Teeth BD 50R  BD 16L  20 TPL 27 Teeth 90°  BD 25L  30 TPL 90°  BD 35L  40 TPL 55 Teeth 90°  BD 35L  40 TPL 55 Teeth 90°  BD 35L	BD 16R   16 TP1   27 Teeth   50°   5 TP1   4 Teeth   50°   6	BD 16R   15 TP1   27 Teeth   50°   50°   51°	BD 16R   27 Teeth   90°   51Pl   4 Teeth   90°   52 TPl   4 Teeth   90°   52 TPl   52 Teeth   90°   52 TPl   52 Teeth   50°	BD 16R   25 TPL   SD 20R   20 TPL   41 Teeth   S0°   SD 20R   20 TPL   41 Teeth   S0°   SD 20R   20 TPL   41 Teeth   S0°   SD 25R   25 TPL   SD 25R   25 TPL   SD 25R   25 TPL   SD 25R   ST TEETH   S0°   S0°	BD 16R   27 Teeth   SD 20R   20 TPL   41 Teeth   SD 20R   25 TPL   SD 30R   30 TPL   SD 10R   31 Teeth   SD 25R   25 TPL   SD 30R   30 TPL   SD 10R   30 T	BD 16R   27 Teeth   AD 16R   27 Teeth   AD 16R   27 Teeth   30°   AD 20R   20° TP1   41 Teeth   30°   AD 25R   42 Teeth   30°   AD 25R   42 Teeth   30°   AD 25R   AD 25R

DIAN	DIAMOND KNURLS — 30° SPIRAL											
	BF 20	20 T.P.I. 34 Teeth 90° Female	SF 20	20 TPI 41 Teeth 90° Female	AF 20	20 T.P.i. 41 Teeth 90° Fernale						
	BF 25	25 T.P.I. 42 Teeth 90° Female	SF 25	25 TPJ. 51 Teeth 90° Female	AF 25	25 T.P.L 51 Teeth 90° Female						
FEMALE knurts have DEPRESSED points and produce	BF 30	30 T.Pi. 52 Teeth 90° Female	SF 30	30 T.P.I. 61 Teeth 90° Female	AF 30	30 T.P.I. 61 Teeth 90° Female						
a male impression. Diamond MALE knurts have RAISED	BF 50	50 T.P.I. 86 Teeth 70° Female	SF 50	50 T.P.I. 102 Teeth 70° Female	AF 50	50 T.P.I. 102 Teeth 70° Female						
points and produce a female impression. PITCH IS MEASURED	BM 20	20 T.P.I. 34 Teeth 90° Male	SM 20	20 T.P.I. 41 Teeth 90° Male	AM 20	20 T.P.I. 41 Teeth 90° Male						
PERPENDICULARLY to the TEETH.	BM 25	25 T.P.I. 42 Teeth 90° Male	SM 25	25 T.P.I. 51 Teeth 90° Male	AM 25	25 T.P.I. 51 Teeth 90° Male						
	BM 30	30 T.P.I. 52 Teeth 90° Male	SM 30	30 T.P.I. 61 Teeth 90° Male	AM 30	30 T.P.I. 61 Teeth 90° Male						
	BM 50	50 T.P.I. 86 Teeth 70° Male	SM 50	50 T.P.I. 102 Teeth 70° Male	AM 50	50 T.P.I. 102 Teeth 70° Male						



# REED-RICO® Standard Knurls

C Se	ries	B Sei	ries	S Se	ries	A S	eries	F Sei	ries
DIA.	1/2"	DIA.	5/8"	DIA.	3/4"	DIA.	3/4"	DIA.	7/8"
WIDTH		WIDTH		WIDTH			3/8"	WIDTH	3/8"
HOLE	3/16"	HOLE	1/4	HOLE	1/4"	HOLE	1/4"	HOLE	1/4"
	D	IAMETF	RAL PI	TCH KI	NURLS	S — ST	RAIGH	IT	
CS-64 DI	P	BS-64 D	P	SS-64 DF	•	AS-64	DP	FS-64 DF	•
CS-96 DI	P	BS-96 D	P	SS-96 DF	•	AS-96	DP	FS-96 DF	•
CS-128 D	P	BS-128 [	)P	SS-128 D	P	AS-128	DP		
CS-160 D	P	BS-160 [	)P	SS-160 D	P	AS-160	DP		·
DI	AMET	RAL PIT	СН К	NURLS	— DI/	AGONA	L 30°	SPIRA	L
		BDR-64	DP	SDR-64 [	)P	ADR-64	DP		
CDR-96	DP	BDR-96	DP	SDR-96 [	)P	ADR-96	DP		
CDR-128	DP	BDR-128	DP	SDR-128	DP	ADR-12	8 DP		
CDR-160	DP	BDR-160	DP	SDR-160	DP	ADR-16	O DP		
		BDL-64	DP	SDL-64 [	)P	ADL-64	DP		
CDL-96 I	DP	BDL-96	DP	SDL-96 [	)P	ADL-96	DP		
CDL-128	DP	BDL-128	DP	SDL-128	DP	ADL-12	B DP		
CDL-160	DP	BDL-160	DP	SDL-160	DP	ADL-16	O DP		

# Comparison of REED-RICO Circular and Diametral Pitch Straight Knurling

	rcular Pitch Sys	tem		Diametra	Pitch System	
Samples of Knurling	Common TPI	Circular Pitch	Samples of Knurling	Diametral Pitch	TPI	Circular Pitch
	12	.0833				
	16	.0625				
	20	.0500		64	20.4	.0491
	25	.0400				
	30	.0333		96	30.6	.0327
	35	.0286				
	40	.0250		128	40.7	.0245
	50	.0200		160	50.9	.0196
	80	.0125				

# Notes