



notes for tolerances

all distances between holes
without tolerances

fits : $\pm 0,02$ mm
threads : $\pm 0,1$ mm
holes : $\pm 0,2$ mm
countersunks : $\pm 0,2$ mm

N6